

Recreational Waters Bacterial (Enterococci) Monitoring Program

Site Status Overview 2022 - Great Southern Region Local Government Authorities

Local Government / Managing Authority	Water Body	Site Code	Site Name	GPS Deci-Degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sample Analysis Period	Sanitary Assess Category (SAC)	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2022-2023
Albany (City of)	Harbour	AC3/009	Boatshed Beach - Princess Royal Harbour	-35.031225, 117.889195	1. New	2018-2019	6					Nov - May	Moderate		Collect 5-10 rainfall (w/in 24-48hrs) & SW drain samples	13
Albany (City of)	Inlet	AC3/007	Emu Beach - Oyster Harbour	-34.996985, 117.947777	1. New	2018-2019	5					Nov - May	Moderate		Collect 5-10 rainfall (w/in 24-48hrs) & SW drain samples	13
Albany (City of)	Ocean	AC3/010	Frenchman Bay	-35.092025, 117.949624	1. New	2018-2019	6					Nov - May	Low			13
Albany (City of)	Ocean	AC3/032	Ellen Cove (Jetty) - Middleton Beach	-35.025484, 117.918298	1. New	2018-2019	5					Nov - May	Moderate		Collect 5-10 rainfall (24-48hrs) samples	13
Albany (City of)	Lake	AC3/038	Lake Mullocullop	-34.721639, 118.471921	1. Proposed	2021-2022							Low			5
Albany (City of)/ DWER	Harbour	AC3/026	Oyster Harbour - 6021174 - AOH2 - SE	-34.98291, 117.965439	2. Active (Non-core)	2018-2020	34	2	A	20	11	All year	Not Avail			0
Albany (City of)/ DWER	Harbour	AC3/027	Oyster Harbour - 6021260 - AOH12 - SW Yak Crk	-34.982958, 117.943254	2. Active (Non-core)	2018-2022	51	30	A	140	10	All year	Not Avail			0
Albany (City of)/ DWER	Harbour	AC3/028	Oyster Harbour - 6021176 - AOH4 - NW Bay Rd	-34.962303, 117.954409	2. Active (Non-core)	2018-2022	34	36	A	140	10	All year	Not Avail			0
Albany (City of)/ DWER	Harbour	AC3/029	Oyster Harbour - 6021177 - AOH5 - NW - Low Kg	-34.950692, 117.955238	2. Active (Non-core)	2018-2022	52	30	A	140	10	All year	Not Avail			0
Albany (City of)/ DWER	River	AC3/030	Oyster Harbour - 6021254 - AOH6 - NE - Kalg Rvr Bdg	-34.948953, 117.977734	2. Active (Non-core)	2018-2022	52	95	B	727	43	All year	Moderate			0

Recreational Waters Bacterial (Enterococci) Monitoring Program

Site Status Overview 2022 - Great Southern Region Local Government Authorities

Local Government / Managing Authority	Water Body	Site Code	Site Name	GPS Deci-Degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sample Analysis Period	Sanitary Assess Category (SAC)	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2022-2023
Albany (City of)/ DWER	River	AC3/031	Lower Bridge - 6021063 - Lower King Rvr Bdg	-34.94397, 117.947702	2. Active (Non-core)	2018-2022	51	95	B	466	46	All year	Moderate			0
Albany (City of)/ DWER	Harbour	AC3/025	Oyster Harbour - 6021173 - AOH1 - S - Middle	-34.983231, 117.955659	3. Inactive (Non-core)	2018-2021	34	7	A	35	14		Not Avail			0
Cranbrook (Shire of)	Lake	CR3/001	Nunijup Lake	-34.4054, 117.406573	1. Proposed	2021-2022	3					Nov - May	Moderate		Collect 5-10 rainfall (24-48hrs) samples	13
Cranbrook (Shire of)	Lake	CR3/002	Lake Poorrarecup	-34.419673, 117.233831	1. Proposed	2021-2022	3					Nov - May	Low		Annual SIR Review	13
Denmark (Shire of)	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	-34.975896, 117.366096	1. Program	2016-2021	15	90	B	294	46	Nov - May	Moderate			13
Denmark (Shire of)	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	-34.975896, 117.366096	1. Program	2016-2021	18	270	C	2430	176	All year	Moderate		Collect 5-10 rainfall (24-48hrs) samples	13
Denmark (Shire of)	Ocean	DK3/025	Peaceful Bay - Ocean	-35.041714, 116.92976	1. Program	2017-2022	47	2	A	140	10	All year	Moderate		Collect 5-10 SW drain samples	13
Denmark (Shire of)	Ocean	DK3/025A	Peaceful Bay - Ocean (South)	-35.042113, 116.929721	1. Program	2017-2022	47	12	A	140	10	All year	Moderate		Collect 5-10 SW drain samples	13
Denmark (Shire of)	Ocean	DK3/025B	Peaceful Bay - Ocean (North)	-35.041352, 116.929873	1. Program	2017-2022	47	9	A	140	10	All year	Moderate		Collect 5-10 SW drain samples	13
Denmark (Shire of)	River	DK3/002	Denmark River - Mokare Bridge	-34.968901, 117.365867	1. Proposed	2022	1						Not Avail		SIR Required – Liaise w/ DoH	13



Recreational Waters Bacterial (Enterococci) Monitoring Program

Site Status Overview 2022 - Great Southern Region Local Government Authorities

Local Government / Managing Authority	Water Body	Site Code	Site Name	GPS Deci-Degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sample Analysis Period	Sanitary Assess Category (SAC)	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2022-2023
Denmark (Shire of)	Bore	DK3/035	Peaceful Bay - Central Ave Bore	-35.039025, 116.926137	2. Active (Non-core)	2017-2022	46	0	A		10	All year	Not Avail			0
Denmark (Shire of)	Bore	DK3/038	Peaceful Bay - Fourth Ave Bore	-35.038081, 116.926452	2. Active (Non-core)	2017-2022	46	0	A		10	All year	Not Avail			0
Denmark (Shire of)	Bore	DK3/039	Peaceful Bay - Fith Ave Bore	-35.037803, 116.924256	2. Active (Non-core)	2017-2022	46	0	A		10	All year	Not Avail			0
Denmark (Shire of)	Bore	DK3/040	Peaceful Bay - Bore Tap Caravan Park	-35.040626, 116.927578	2. Active (Non-core)	2017-2022	46	16	A	140	10	All year	Not Avail			0
Denmark (Shire of)	Creek	DK3/021	Peaceful Bay - Supply Creek	-35.041304, 116.925934	2. Active (Non-core)	2017-2022	46	1000	D	31803	1530	All year	Not Avail			0
Denmark (Shire of)	Creek	DK3/024	Peaceful Bay - Creek/Drain	-35.041636, 116.929175	2. Active (Non-core)	2017-2022	46	680	D	1791	300	All year	Not Avail			0
Denmark (Shire of)	Drain	DK3/023	Peaceful Bay Open Drain - Foot Bridge	-35.041127, 116.928611	2. Active (Non-core)	2017-2022	46	940	D	4683	564	All year	Not Avail			0
Denmark (Shire of)	Drain	DK3/026	PeacefulBay Open Drain - Peppermint Rd	-35.037608, 116.921235	2. Active (Non-core)	2017-2022	12	540	D	1145	220	All year	Not Avail			0
Denmark (Shire of)	Drain	DK3/027	Peaceful Bay Drain - Cnr West Ave/Fourth Ave	-35.037982, 116.923731	2. Active (Non-core)	2017-2022	22	460	C	980	191	All year	Not Avail			0
Denmark (Shire of)	Drain	DK3/028	Peaceful Bay Drain - Cnr East Ave/Fourth Ave	-35.037566, 116.927596	2. Active (Non-core)	2017-2022	18	1400	D	15763	1309	All year	Not Avail			0

Recreational Waters Bacterial (Enterococci) Monitoring Program

Site Status Overview 2022 - Great Southern Region Local Government Authorities

Local Government / Managing Authority	Water Body	Site Code	Site Name	GPS Deci-Degrees	Monitoring Category	Result Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sample Analysis Period	Sanitary Assess Category (SAC)	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2022-2023
Denmark (Shire of)	Drain	DK3/029	Peaceful Bay Drain - Caravan Park	-35.04009, 116.929362	2. Active (Non-core)	2017-2022	12	440	C	500	144	All year	Not Avail			0
Denmark (Shire of)	Drain	DK3/042	Nornalup - Drain Outlet	-34.990902, 116.815937	2. Active (Non-core)	2017-2022	27	150	B	228	70	Nov - May	Not Avail			0
Denmark (Shire of)	Drain	DK3/042	Nornalup - Drain Outlet	-34.990902, 116.815937	2. Active (Non-core)	2017-2022	46	250	C	1750	95	All year	Not Avail			0
Denmark (Shire of)	Inlet	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	-35.02107, 117.327082	2. Active (Non-core)	2016-2021	9	155	B	700	80	Nov - May	Low			5
Denmark (Shire of)	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	-34.969706, 117.368831	2. Active (Non-core)	2016-2021	15	100	B	149	53	Nov - May	Moderate			5
Denmark (Shire of)	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	-34.969706, 117.368831	2. Active (Non-core)	2016-2021	18	280	C	440	113	All year	Moderate			5
Denmark (Shire of)	Reservoir	DK3/022	Peaceful Bay - Water Supply Dam	-35.040871, 116.927578	2. Active (Non-core)	2017-2022	46	820	D	15700	927	All year	Not Avail			0
Denmark (Shire of)	River	DK3/054	Denmark River - Berridge Park	-34.959994, 117.357211	2. Active (Non-core)	2016-2021	15	1150	D	2018	402		High			5
Denmark (Shire of)	Tap	DK3/031	East Ave (Lot 163) - Garden Tap	-35.039597, 116.928095	2. Active (Non-core)	2017-2022	45	34	A	88	28	All year	Not Avail			0
Denmark (Shire of)	Tap	DK3/036	Peaceful Bay - Third Ave Lot 92 Garden Tap	-35.038736, 116.92496	2. Active (Non-core)	2017-2022	45	28	A	84	23	All year	Not Avail			0
Katanning (Shire of)	Lake	KT3/013	Lake Ewlyamartup	-33.693108, 117.736472	1. Proposed	2021	2						Moderate		Collect 5-10 SW Drn, riverine & rainfall (24-48 hrs) samples	13